

LOUISIANA DEPARTMENT OF ENVIRONMENTAL QUALITY  
INCIDENT REPORT

Incident ID: 123466

**Incident Description**

**Incident Type:** Release/Spill, Facility Air Release  
**Incident Date:** 5/15/2010 16:35:00  
**Parish:** West Baton Rouge  
**Municipality:** Port Allen  
**Location:** Placid Refining - 1940 LA Hwy 1 N - Port Allen  
**Lat/Lon:**  
**Basin/Segment:**  
**Substance(s):**  
**Media Impacted:** Air  
**Incident Desc:** s10-1622 Unscheduled maintenance...requiring shutdown of FCC Unit...possible flaring...cj

**Incident Status**

**Lead Investigator:** Serugudi Mani  
**Incident Region:** Capital  
**Incident Status:** Closed  
**Followup Status:** Closed  
**As Of:** 5/28/2010 00:00:00

**Incident Reporter 1**

**Received By:** Carla James  
**Received Date:** 5/17/2010 07:17:00  
**Dispatch #:** s10-1622  
**Reported By:** Brian Bergeron  
**Phone:** 225-387-0278 (Work phone number)  
**Reporter Title:**  
**Organization:** Placid Refining  
**Address:** 1940 LA Hwy 1 N  
  
**Municipality:** Port Allen  
**State:** LA  
**Zip Code:** 70767  
**Comments:** 741A...cj

LOUISIANA DEPARTMENT OF ENVIRONMENTAL QUALITY  
INCIDENT REPORT

Incident ID: 123466

**Incident Source 1**

**Source Name:** Placid Refining Co LLC - Port Allen Refinery  
**Address:** 1940 Hwy 1 N  
(portion of)

**Municipality:** Port Allen

**State:** LA

**Phone:** 2253870278 (Work phone number)

**Parish:** West Baton Rouge

**AI #:** 2366

**Related Permits:**

**Comments:** unscheduled shut down of FCCU and flaring of off gases. Courtesy call fo flaring. 5/15/10 4:35 PM. srm  
Written report was received 5/27/10 at CRO. NO RQ exceedances from this flaring. The packing on the slide valve stem in the Regenerator side of FCCU failed and had to shut down the unit and flaring ensued The valve was removed and sent for repair. srm